

December 31, 1994

Remington Arms Company, Inc.
Attn: Jack Kast, Product Service
14 Hoefler Ave.
Ilion, NY 13357

Re: Model 700 - 300 Mag.
S/N # B6763551

Dear Mr. Kast:

Thank you for answering my letter. I am sending my rifle herewith for your examination.

As I said in my initial letter, this rifle discharged when I pushed the safety from the "SAFE" to the "FIRE" position. I was preparing to unload when it went off. I am certain that my fingers were behind the trigger guard and did not come in contact with the trigger; it fired the instant the safety hit the "FIRE" position. On your examination you will find that the trigger pull has been increased. The gunsmith I took it to after the incident did that as a precautionary measure after his examination was non-conclusive.


Please let me know the results of your examination before returning the rifle. If your examination is generally non-conclusive or non-specific, I would like a quote from you to replace the entire trigger and safety assemblies at my expense.

My return information is:

Thad S. Miner
c/o Miner - Dederick Construction Corp., Inc.
1532 Peden
Houston, Texas 77219
(713) 529-3001

Thanks again for your promptness in expediting my concern.

Sincerely,



Thad S. Miner