

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 95-02685

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/12/95

01/23/95

WZ 8-75

6891706

700 30-06

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

MCCLELLANDS GUN SHOP
DIVISION OF REMCO
1533 CENTERVILLE ROAD
DALLAS TX 75228

SHIP TO:

MCCLELLANDS GUN SHOP
DIVISION OF REMCO
1533 CENTERVILLE ROAD
DALLAS TX 75228

CUST NO: 006612 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

2/25/95

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE 20.0
EXCISE
TAX
INSURANCE
UPS 8.0
PARCEL POST
TOTAL 28.0

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5				F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Rifle mfg 1975 When rec'd the rifle was in operation, the trigger would not make contact. Examination revealed that the bolt stop return, was safety cam, and trigger are covered with a heavy sticky substance. All other components are right up and not functioning as designed.

PARTS

COMMENTS

This rifle has been properly maintained. Explain to customer trigger assembly. Clean the action at 1/2 the normal cost as a gesture of good will. JD Adams

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTEP
LSE					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1.

PS04123