

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

MODEL AND GRADE

ORDER

05/10/91

05/13/91

PI 6-88

A6310434

700 243 WIN

ADL

R

91-10741

ACCESSORIES

W/STUDS

L/REAR SIGHT

FROM:

THE MATTHEWS GROUP
709 COUNTRY LANE
HOUSTON

TX 77024

SHIP TO:

THE MATTHEWS GROUP
709 COUNTRY LANE
HOUSTON

TX
77024

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

Fires when bolt is closed - on chambered rd

MAIN FAULT

Cannot duplicate complaint - many attempts were made to duplicate with dummy round in chamber - firing pin did not fall. Trigger assembly is contaminated with sticky residue, however, gun - safety can move slowly on receiving. Trigger pull 5 pounds, rear - lift .009". Rifle will not be made to malfunction.

PARTS

Offer to clean present trigger assembly, if possible, or we can install a new trigger assembly at a normal cost, as a gesture of good-will if it will better restore confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE