

THE MATTHEWS GROUP

April 29, 1991

(REF) 91E-COM89 - 1

Remington Arms
Arms Service Division
14 Hoefler Avenue
Ilion, New York 13357

(TEL) 315-895-7791

Dear Sirs:

I have enclosed one Remington 243 Winchester Model 700 ADL rifle, serial number A6310434, for your repair or replacement. The rifle is misfiring because the firing pin is striking the shell in the chamber at the time the bolt is closed rather than when the trigger is pulled. This malfunction does not occur every time the bolt is closed without a shell in the chamber, but has consistently occurred when the bolt is closed on a chambered round.

Thank you for your attention to this matter. If you have any questions, please contact me. I look forward to your response.

Best regards,

Kennie E. Matthews
Kennie E. Matthews

(FAX) 713-464-5025

709 Country Lane

Houston, Texas 77024

713-464-9900

PS04141