

Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00065110	Description/Serial Number C6496013	Repairman - Robert Frink
Account # - R-	Model 700 Center Fire with 22 inch barrel Caliber: 7MM-BDL	Date Received - 5/12/2003
Customer PHILLIP MARTIN 10245 BENT MOUNTAIN ROAD BENT MOUNTAIN, VA 24059 US		Estimate Date - 5/8/2003 Current Date - 5/15/2003
Phone (H) (540)-387-6104 Phone (W) (540)-529-9893 Xcell		Return To PHILLIP MARTIN 10245 BENT MOUNTAIN ROAD BENT MOUNTAIN, VA 24059 US
	Fax	Email pmartin@co.roanoke.va.t

Reported	Problem	Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FOR
M992	DELAYED FIRING		

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000118	GR-CLEAN	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		22	22	0	

Problem/Notes	Parts inside the trigger assembly covered with a brown sticky substance. Components working sluggish. Checkover, clean action and replace the trigger assembly for \$20.00. D.S.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date