

Repair Order Number



|                                                                            |                                                                             |                                                       |
|----------------------------------------------------------------------------|-----------------------------------------------------------------------------|-------------------------------------------------------|
| Repair Order Number<br>RE00061431                                          | Description/Serial Number<br>ML075984                                       | Repairman - Bruce Travis<br>Date Received - 2/11/2003 |
| Account # - R-                                                             | Model 700ML Center Fire Caliber: 50<br>CAMO                                 | Estimate Date -<br>Current Date - 4/1/2003            |
| Customer<br>JAMES MITTS<br>1761 MAPLEGROVE ROAD<br>MOUNT ORAB. OH 45154 US | Return To<br>JAMES MITTS<br>1761 MAPLEGROVE ROAD<br>MOUNT ORAB. OH 45154 US |                                                       |
| Phone (H) (937)-444-2981 XHOM<br>Phone (W) (888)-686-1551 XWRK             | Fax<br>Email                                                                |                                                       |

| Problems |                                              |       |                              |
|----------|----------------------------------------------|-------|------------------------------|
| Reported |                                              | Found |                              |
| M123     | FORWARD TO PRODUCT SERVICE<br>FOR INSPECTION | M123  | FORWARD TO PRODUCT SERVICE F |
| M992     | FIRES WHEN TAKEN OFF SAFE                    |       |                              |

|                       |                               | Repair             |                      |                      |                   |
|-----------------------|-------------------------------|--------------------|----------------------|----------------------|-------------------|
| Material #            | MaterialDesc                  | Quantity<br>Needed | Quantity<br>From Inv | Quantity<br>From Kit | Warranty<br>(Y/N) |
| <b>Part</b>           |                               |                    |                      |                      |                   |
| F99294                | 700 ML SS TRIG ASSB           | 1                  | 1                    | 0                    | N                 |
| <b>Part Total:</b>    |                               | 1                  | 1                    | 0                    |                   |
| <b>Service</b>        |                               |                    |                      |                      |                   |
| 4000104               | ARMS SERV SHIPPING & HANDLING | 0                  | 0                    | 0                    | N                 |
| <b>Service Total:</b> |                               | 0                  | 0                    | 0                    |                   |

|                                                                                                      |       |       |      |        |         |
|------------------------------------------------------------------------------------------------------|-------|-------|------|--------|---------|
| ProblemNotes trigger adjusting screws altered replace trigger assm at 1/2 msp go ahead mfg date 6/97 |       |       |      |        |         |
| Repairman                                                                                            | Proof | Clean | Test | Target | Pattern |
| Gallery Tester                                                                                       | Date  | Date  | Date | Date   | Date    |