## Remington.

## TRACKING DOCUMENT

## Repair Order Number



Repair Order Number

RE00074381 Account # - R- Description/Serial Number

A6840708

Model 700 Center Fire with 24 inch

barrel Caliber: 7 MM REM MAG BDL

Estimate Date - 12/19/2003

Repairman -Herb Brown

Date Received - 1/14/2004

Current Date - 1/17/2004

Customer

DONALD MCCRUMB 7001 MIERAS ROAD

YAKIMA. WA 98901 US

Return To

DONALD MCCRUMB 7001 MIERAS ROAD

YAKIMA. WA 98901 US

Phone (H)

Reported M123

M992

(509)-452-8140

Fax **Email** 

Phone (W)

FOR INSPECTION

FORWARD TO PRODUCT SERVICE

M123

FORWARD TO PRODUCT SERVICE FOR

FIRES ON SAFE

|                   | <u>MaterialDesc</u>                                      | Quantity<br>Needed | <u>Quantity</u><br>From Inv | Quantity<br>From Kit | Warranty<br>(Y/N) |
|-------------------|--|--------------------|-----------------------------|----------------------|-------------------|
| Part Part Service | Total:   | 1                  | 0                           | 0                    |                   |
| 4000294           | GR-CHECK TPA<br>ARMS SERV SHIPPING & HANDLING<br>GR-TEST | 1 0                | 1 0                         | 0                    | Y<br>Y            |
| Service           |  |                    | 1                           | <u>0</u>             | Y                 |

**ProblemNotes** 

Upon receipt we coild not duplicate reported concern. action and trigger assm. covered with dirt and dust. Poor maintenance. Replace trigger assm. spec.

| Repairman      | Proof | Clean | Test | Target | Pattern |
|----------------|-------|-------|------|--------|---------|
| Gallery Tester | Date  | Date  | Date | Date   | Date    |