

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product
ServiceORDER
R 94-21933

INITIAL CUSTOMER ORDER NO.

FES

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
07/25/94	07/25/94	CU 4-71	6418931		700 222 REM ADL
ACCESSORIES		SCOPE BASE			
W/STUDS		L/REAR SIGHT			

FROM

SHIP TO:

MOORE, DENNIS F.
RD 2 BOX 104B
PROCTOR

WV 26055

MOORE, DENNIS F.
RD 2 BOX 104B
PROCTORWV
26055

CUST NO: 100474 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE	80.00
EXCISE	
TAX	
INSURANCE	
UPS	8.00
PARCEL POST	
TOTAL	88.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.				D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt, the bolt separation, trigger, and even safety were found with a heavy gummy substance. All components working slightly. Rifle in operation. Examination also revealed that the trigger separation was apparent to have been a-act. Rifle has been poorly maintained.

PARTS

COMMENTS

#26345

Refuse to complete trigger assembly and clean the action at 1/2 round. Separated, as a gesture of good will.

Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PAT
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV

to A/S

8/15/94