

RECEIVING AND ESTIMATING REPORT

COMMENTS

*to Product Service.*ORDER
R 94-07892INITIAL
FJB

CUSTOMER ORDER NO.

W/ BOTTOM HALF OF 1 SCOPE RING

DATE RECEIVED

02/25/94

DATE OPENED

03/04/94

DATE CODE

BC 1-82

SERIAL NUMBER

B6370175

NEW SERIAL NUMBER

MODEL AND GRADE

700 243

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

MCQUEEN, MIKE
1609 ROLESAN LA
JONESBORO

AR 72401

SHIP TO:

MCQUEEN, MIKE
1609 ROLESAN LA
JONESBOROAR
72401

CUST NO: 093384 C.D.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☒ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Letter of 1/8/92 upon arrival, could not duplicate customer concern, however, disassembled trigger assembly, and found pin worn by an amount with a safety rifle customer. Trigger pin adjustment has been set to deliver max. minimum spec.

PARTS

Trigger pin - 2 1/2"
pin tip - .010

COMMENTS

*Replace complete trigger assembly
& clean rifle w/ 1/2 normal replacement
cost in spirit of good will*
Go ahead

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS04238