



April 04, 1994

Called Customer 5:24p
April to return
Dear Remington -



I own a Model 700 BDL in 30-06 CALIBER.

Serial # 375649 (This rifle was manufactured in 1968 I believe.)


Please issue a recall notice to allow this rifle to be used. I can't use it since it has twice, in front of witnesses, discharged while I pushed the safety lever forward. Once into the ground beside my children and once into the side of my Chevy Suburban - I had to have the hole repaired.

Please tell me the steps you will take to repair this rifle - a problem that is in the design, not the age of the rifle.

You may call me or write - but please
don't explain there's nothing wrong with it.
There is and I want it fixed.

I have photocopied this letter for
my records and my attorneys'.

Sincerely



Larry McGlocklin

1700 Capri Lane

Seabrook, TX 77586-2926

(713) 474-4407 - Home

(713) 447-5298 - Work

(713) 447-5299 - Fax