

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-02337

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE	
01/18/94	01/19/94	LD 2-77	A6413886		700 30-06	BDL
ACCESSORIES W/STUDS						

FROM:

Steph
MCCLELLANDS GUN SHOP
DIVISION OF REMCO
1533 CENTERVILLE ROAD
DALLAS TX 75228

SHIP TO:

MCCLELLANDS GUN SHOP
DIVISION OF REMCO
1533 CENTERVILLE ROAD
DALLAS TX 75228

CUST NO:006612 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER W/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

Product Service

REPAIR CHARGE *25.00*
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5				F4
WOOD			C1		E5	F5
METAL			C2			

MAIN FAULT

*Upon receipt, unable to duplicate Customer Concern.
Examination revealed that the trigger adjustment screw has been fully
retracted, turned the stop screw up, and now trigger has been worked.
Customer request more work, but safety. See bill, receipt. 009
by [signature] 4/15/94.*

PARTS

COMMENTS

*Repair complete trigger assembly
with no bolt lock, and Chamber action is
1/2 normal replacement cost, inspection &
good will*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
<i>P.C.</i>					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

14-0425 REV 1/92

PS04251