

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-15013

INITIAL CUSTOMER ORDER NO.

FDC

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

05/04/94

05/05/94

BI 1/88

A6253284

700

220250

REM VARM.

ACCESSORIES

W/STUDS

SCOPE BASE

1 SWIVEL

FROM:

SHIP TO:

MAJOR TRUE VALUE
JACKSON ST.
HOPE

IN 47240

MAJOR TRUE VALUE
JACKSON ST.
HOPEIN
47240

CUST NO 996940 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE *20.00*
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

*Upon receipt, we could not duplicate the Customer's concern.
With 1988 Remington-Union Carbide 700 and trigger assembly as found with a
heavy primary spring, subsonic. Shot on about 100 yds. Bolt stop when would not
release.*

PARTS

COMMENTS

#26345 Trigger Assembly

*Trigger pull measured 5.5 to 5.7 lbs
and released, same with 5.105*

*Replaced complete trigger assembly and
clean action at 1/2 normal replacement cost
at gunsmith's shop.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
TAL					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/84

to A/S 5/19/94