

RECEIVING AND ESTIMATING REPORT

COMMENTS

To Product Service

ORDER

R 94-03871

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/31/94

02/01/94

DX 9-73

6625396

700

243

BDL

ACCESSORIES

W/STUDS

L/SIGHTS

FROM

MAIDEN, GARY
HWY 522
POTNEY

KY 40865

SHIP TO:

MAIDEN, GARY
HWY 522
POTNEYKY
40865

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

CUST NO: 091642 C.D.D.

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

2500

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt rifle inoperative, would not cock. Changing the bolt
allows the firing pin to follow down. Examination revealed that the trigger only on
trigger stop screws have been tampered with instead the firing pin. Firing pin has
been removed, and the trigger pin removed below 2 lb. Bolt stop release and action
had a good cleaning, bolt release will not stick from being jammed up with a
sticky substance. Rifle mfg 1973

Before complete trigger assembly & clean
action of 12 round automatic cost, as a
gift to Go Ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
DATE	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/82

PS04288