

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-13741INITIAL
FPS CUSTOMER ORDER NO.

CALL TAG ATTN: FRED MARTIN

DATE RECEIVED 04/20/94	DATE OPENED 04/21/94	DATE CODE AO 3-77	SERIAL NUMBER A6430465	NEW SERIAL NUMBER	MODEL AND GRADE 700 308 WIN BDL
ACCESSORIES W/STUDS					

FROM:

MACINOWSKI, RICHARD
5422 VICARIS ST
PHILADELPHIA

PA 19128

SHIP TO:

MACINOWSKI, RICHARD
5422 VICARIS ST
PHILADELPHIAPA
19128

CUST NO: 096334 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION					REPAIR CHARGE
☐ NEW					EXCISE
☐ LIGHTLY WORN					TAX
☐ WORN					INSURANCE
☐ VERY WORN					UPS
☐ UNREPAIRABLE					PARCEL POST
☐ MARRED					TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon Receipt Could Not Duplicate However Trigger
Was Slight In Operation. Extremely Oily
Trigger Has Been Adjusted Out Of Factory Specs.

PARTS	COMMENTS					
	REPLACE TRIGGER CLEAN ACTION AT 1/2 NORMAL CHARGE AS GESTURE OF GOOD WILL					
	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 1/94

PS04292

RECEIVING AND ESTIMATING REPORT

COMMENTS

CALL TAG ATTN: FRED MARTIN

ORDER
94-13741INITIAL
FPS

CUSTOMER ORDER NO.

DATE RECEIVED

04/20/94

DATE OPENED

04/21/94

DATE CODE

AD 3-77

SERIAL NUMBER

A6430465

NEW SERIAL NUMBER

MODEL AND GRADE

700

308 WIN

BDL

ACCESSORIES

W/STUDS

FROM:

MACINOWSKI, RICHARD
5422 VICARIS ST
PHILADELPHIA

PA 19128

SHIP TO:

MACINOWSKI, RICHARD
5422 VICARIS ST
PHILADELPHIAPA
19128

CUST NO: 096334 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

E1

F1

BOLT ASSY.

B3

E2

F2

BARREL ASSY.

B4

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Upon Receipt Could Not Duplicate However Trigger
Was Sluggish In Operation. Extremely Oily
Trigger Has Been Adjusted Out Of Factory Specs.

PARTS

COMMENTS

Replace Trigger Clean
Action At 1/2 Normal
Charge As Gesture Of
Good Will

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/84