

## RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 98-26146

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

2/03/98

12/07/98

EI 10-76

A6363115

700 270

ADL

ACCESSORIES

SCOPE BASE

L/SIGHTS

L/STUDS

FROM:

SHIP TO:

MAGALLANES, JO ANN  
803 S MAIN  
JACKSBORO

TX 76458

MAGALLANES, JO ANN  
803 S MAIN  
JACKSBOROTX  
76458

CUST NO: 198094 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW  
☐ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARRED

Prod. Serv.

REPAIR CHARGE 35.00  
EXCISE  
TAX  
INSURANCE  
UPS 8.00  
PARCEL PDST  
TOTAL 43.00

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|------------------|------|----------|--------|----------|-----|---------|
| CYCLE            | A1   | B1       |        |          |     |         |
| TRIGGER GROUP X  |      | B2       |        |          | E1  | F1      |
| BOLT ASSY.       |      | B3       |        |          | E2  | F2      |
| REL ASSY.        |      | B4       |        |          | E3  | F3      |
| REC. ASSY.       |      | B5       |        | D2       | E4  | F4      |
| WOOD             |      |          | C1     | D3       | E5  | F5      |
| METAL            |      |          | C2     |          |     |         |

MAIN FAULT

Upon receipt the rifle was in operation, the bolt stop valve, rear sight cam & trigger were seized up from being covered with a sticky substance. Mag. Spring weak & other duty.

PARTS

COMMENTS

# 26345

Replace the compact trigger  
cam & clean action at 1/2  
the normal repair charge  
Go ahead

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

PS04311