

Repair Order Number



<b>Repair Order Number</b> RE00073172	<b>Description/Serial Number</b> S6733660	<b>Repairman -</b> Dale Lewis
<b>Account # - R-</b>	<b>Model 7 Center Fire Caliber:</b> 243 SS	<b>Date Received -</b> 11/26/2003
	<b>SYNTHETIC</b>	<b>Estimate Date -</b>
		<b>Current Date -</b> 12/11/2003
<b>Customer</b> MARK'S OUTDOOR SPORTS 1400 B MONTGOMERY HIGHWAY  BIRMINGHAM. AL 35216 US		<b>Return To</b> MARK'S OUTDOOR SPORTS 1400 B MONTGOMERY HIGHWAY  BIRMINGHAM. AL 35216 US
<b>Phone (H)</b> (205)-822-2010	<b>Fax</b> (205)-822-2984	
<b>Phone (W)</b>	<b>Email</b>	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	GUN FIRED FROM SAFETY		

Repair					
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
<b>Part</b>					
F97954	7 SS TRIGGER ASSB	1	1	0	Y
<b>Part Total:</b>		1	1	0	
<b>Service</b>					
4000294	GR-CHECK TPA	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000119	GR-TEST	1	1	0	Y
<b>Service Total:</b>		2	2	0	

<b>ProblemNotes</b>	could not duplicate...install new trigger assem at no charge per product service.				
<b>Repairman</b>	<b>Proof</b>	<b>Clean</b>	<b>Test</b>	<b>Target</b>	<b>Pattern</b>
<b>Gallery Tester</b>	<b>Date</b>	<b>Date</b>	<b>Date</b>	<b>Date</b>	<b>Date</b>