

File Number:	16126		Arms Service number:	26346	
Last Name:	MAHONEY'S		First Name:		
Street:	830 SUNSET DRIVE		City:	JOHNSON CITY	
State:	TN	Zip:	37604	Home Ph:	
Work Ph:	423-282-5413	Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4040	Cause:	OTHER - COULD NOT DUPLICATE		
Assigned To:	SUPRY	Classification:	UNJ	UNJ UNC UND	
Settlement Detail:	INSTALL NEW TA AND CLEAN AT SPECIAL PRI		Settlement Amount:	\$0.00	
Date Opened Rem:	4/18/01	Date Opened by P/S:	4/18/01	Caliber:	22250
Date of Incident:		Date Closed:	4/18/01	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	700	Serial:	6830580	Date Code:	BZ
RAMAC:	700	Date Mfgd:	1/1/75	Litigation:	<input type="checkbox"/>
Custody:		PreLitigation:	<input type="checkbox"/>	Obsolete:	<input type="checkbox"/>
Comments:	Could not duplicate customer's concern - All adjustment screw positions have been altered, TA is dirty and coated with sticky residue - both the sear cam and bolt release work sluggishly - Install new TA and clean action at 1/2 normal charges.				
Time of Modification:	11:09:16 AM				
Date of Modification:	4/18/01				