

# Remington

LS/FP		Repair instructions	
Model Number:	700 30-06	Serial Number:	
Are you the original owner?: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		C 6 T 1 7 6 7 6	
Name:	James T Matusek	Date of Purchase:	won at Ducks Unlimited 1990's
Address (No PO Boxes):			
9830 Yawkey St			
City:	Hazelhurst	State:	WI
Phone (Daytime):	715 356 2321	Zip:	54581
E-mail Address:			
Please describe your problem: Rifle <sup>Fires</sup> when I take the safety off without pulling trigger (Happened 3 times once Roped Thumb open). Rifle will not cock some times when I work the action. I had one Hang Fire that cost me a Eight point Buck. Trigger Pull & Travel are at what I like!! IF You Have to adjust Them to Fix my Problem make Trigger Pull as Light as Safety Permits with no Trigger Travel. I DO NOT Think There Should Be any Charges! Problem Started Right out of Box! Problem is the same as Seen on TV and Read about!			
Ammunition Information:			
Manufacturer:	Federal	Type:	30-06 Sprg 150 GR Hi-Shok Soft Point
Other (i.e. bullet weight/type, shot size, powder):			
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	
Firearms Care (Cleaning and Lubrication):			
Brand of cleaning solution used:			
How often do you clean the bore? (Months or Number of rounds)			
How often do you clean the action? (Months or Number of rounds)			
How often do you clean the trigger assembly? (Months or Number of rounds)			
Brand of lubricant used:			
How often do you lubricate the bore? (Months or Number of rounds)			
How often do you lubricate the action? (Months or Number of rounds)			
How often do you lubricate the trigger assembly? (Months or Number of rounds)			
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
Comments:			
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?			
What were the services performed?			

34310