

Remington®



cc: J.E. Preiser

bcc: Q. Hutton

F. Sup'y

REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

March 19, 1990

Mr. John D. McKay
2220 Westover Dr.
Charlottesville, VA 22901

Dear Mr. McKay:

Your letter of February 20, 1990 that was addressed to Mr. Jack Preiser, Director Remington Arms Co., Inc., Wilmington, Delaware, advising of the accidental firing you experienced while using your Model 700 30-06 caliber rifle, has been forwarded to this office for response.

We were indeed sorry to learn of your having a problem of the nature you described.

Generally, the type of problem you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or from inadvertent contact with the trigger when the safety was in the "fire" position.

We would very much like to have the opportunity to examine your rifle so that we can evaluate the cause of your accident. If you are willing to permit us to examine the gun at our laboratory here in Ilion, NY, we will be glad to advise you promptly of our findings.

If this is agreeable to you, please at your convenience, return the rifle via UPS, transportation charges C.O.D. to:


Remington Arms Co., Inc.
Attn: J.A. Stekl
Product Service
14 Hoefler Ave.
Ilion, NY 13357

PS04367

Please be sure to mark the two (2) butt ends of the outside of the package "STEKL" to expedite handling.

Thank you for bringing this matter to our attention, and for affording us this opportunity to be of service to you.

Sincerely,

A handwritten signature in cursive script, appearing to read "J.A. Stekl".

J.A. Stekl, Specialist
Product Service

JAS:tp

Remington Arms Company, Inc.