

Repair Order Number



Repair Order Number RE00090683	Description/Serial Number 381543	Repairman - Bruce Travis
Account # - R-	Model 700 Center Fire Caliber: 7 MM	Date Received - 1/7/2005
	MAG BDL Colored SS	Estimate Date -
		Current Date - 1/13/2005
Customer GANDER MOUNTAIN ATTN GUN PARTS 6939 S 27TH ST FRANKLIN, WI 53132 US		Return To GANDER MOUNTAIN ATTN GUN PARTS 6939 S 27TH ST FRANKLIN, WI 53132 US
Phone (H) (414)-761-1500 X*	Fax	
Phone (W)	Email	

Reported		Problems Found	
M238	CLEAN & INSPECT (SAFETY PROGRAM ONLY)	M123	FORWARD TO PRODUCT SERVICE F
M990	FIRES UPON CLOSING BOLT		

Material #		MaterialDesc		Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part							
F26345		700 TRIG ASSB RH		1	1	0	Y
Part Total:				1	1	0	
Service							
4000119		GR-TEST		1	1	0	Y
4000104		ARMS SERV SHIPPING & HANDLING		0	0	0	Y
4000116		GR-LABOR		20	20	0	N
Service Total:				21	21	0	

ProblemNotes	could not duplicate concern. trigger is dirty and works sluggish. replace trigger assm and clean action under bolt lock program for \$20.00				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date