## To Remington Arms:

I purchased this model 700 in . 308 caliber some 16 years ago, I believe it was 1977. I bought it at the advice of my cousin, who had one, whom I hunted with at that time. His had a problem, of which I impored at the time. His would discharge, when moving the safety from Safe to Fire, live load of course. It was internitted 30 I begin to suspect mine might also have this problem, It was about 1984 when mine discharged, I was not expecting it, though as always had the gon pointed in safe direction. I brought the gun home, never hunted with it again, I called Kemington last year, 1992, and discussed it with a reprensentive, of course they wanted to inspect it. So here it is , July 1993, please call or write to inform me what you found, and to what level of confort I should expect when hunting withit, (Safety)

P.S. The situtation has happen twice, once live, once dry fire.

Thank You,

BILL MEDLIN

1056 Honeyereek ROAD OFF,

Conyers, FIA. 30208

(404) 760.0410 office

(706) 464-4182 Home