

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R93-23584

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

10/29/93

11/02/93

CV 4-79

A6746008

700 6MM

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

SHIP TO:

MCBRIDES GUN SHOP

C/O NBS

2915 SAN GABRIEL/30TH ON LAMAR

AUSTIN

TX 78705

MCBRIDES GUN SHOP

C/O NBS

2915 SAN GABRIEL/30TH ON LAMAR

AUSTIN

TX

78705

CUST NO:006578 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

11-29-93

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☒ MARRED

REPAIR CHARGE 25.00

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

B2

B3

B4

B5

C1

C2

D1

D2

D3

D4

D5

E1

E2

E3

E4

E5

F1

F2

F3

F4

F5

MAIN FAULT

Sent to product service for evaluation

Unable to duplicate customer concern. However, ammunition caused a heavy
striking substance on action and trigger assembly. Bolt stop return has no return
movement. Bolt has been replaced
Numerous times May 1979

PARTS

COMMENTS

Replaced trigger assembly
& clean action at 1/2 normal
replacement cost, as given by good one
go ahead

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92

PS04412