

14 NOFFLER Ave. Ithaca, N.Y. 13357

SUBJECT XP100 SER. # B7533586 2MM BR

DATE 3/7/94

MESSAGE

MESSAGE Our Customer Bill Dinkmeyer - 479-5243
purchased this gun from us recently and has experienced
a significant problem. FREQUENTLY, when chambering
a fresh round and closing the bolt the weapon
fires.

SIGNED

Phaw

REPLY

SIGNED

DATE _____

carbonless**EDIFORM 45 472**

PAK (50 SETS) 4P 472

**SEND PARTS 1 AND 3 INTACT .
PART 3 WILL BE RETURNED WITH REPLY.**

balance, stock and trigger guard.
have proper shape and tip of trigger
guard cause wear.

Q	ANSWER	COMMENTS
		Trigger pull 2 1/2 lbs as rec'd

COMMENTS

Tigger pull 2 1/2 lbs as rec'd

REPAIRMAN

PROOF

CLEAN

TEST

TARGET	DATE	STATUS	REMARKS
1. Complete project plan	2023-10-25	Completed	
2. Review project plan	2023-10-26	In Progress	
3. Implement project plan	2023-10-27	Not Started	
4. Monitor project progress	2023-10-28	Not Started	
5. Report project progress	2023-10-29	Not Started	

PATTERN

~~GALLERY TESTER~~

DATE _____

DATE _____

DATE	
------	--

DATE	
------	--

DATE _____