

RECEIVING AND ESTIMATING REPORT

COMMENTS:

ORDER
R 92-03183INITIAL
JJM

CUSTOMER ORDER NO.

ATTN R POTTER
W/1 SPENT CASEDATE RECEIVED
01/20/92DATE OPENED
01/27/92DATE CODE
XE 12-84SERIAL NUMBER
B6652814

NEW SERIAL NUMBER

MODEL AND GRADE
78 30-06

ACCESSORIES

FROM

MORTON, FRANKLIN
HC 82 74525
ATOKA

OK 74525

SHIP TO:

MORTON, FRANKLIN
HC 82 74525
ATOKA

OK

74525

CUST NO: 056976 C.J.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☒ SLIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT:

As received, trigger assembly and bolt stop were inoperative. Disassembly of rifle revealed trigger assembly and bolt stop to be contaminated with a sticky, gummy substance. The rear-safety cam was stuck to the trigger assembly and plate of the bolt stop was stuck to the receiver cylinder. Disassembly of trigger assembly in all respects appears to have had improper maintenance. Trigger pull & rear lift could not be measured.

PARTS

COMMENTS

Offer replacement trigger assembly.
I would go as a gesture of
goodwill.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8/91

PS04455