



5801 Rhodes Ave.
N.O., La. 70131
12-1-93

Remington-Union Arms Co. Inc.
14 Roepler Ave.
Ilion, N.Y. 13357.
Attn: Repairs Dept.

Dear Sirs;

Enclosed please find a model 700, 30.06, ser. # 6371783.
Last week while on a hunting trip I had an accidental
misfire with this rifle.

The gun had set up for two years, loaded, and had not
been handled until I removed it from its case in the field.
Once in hand, knowing it was loaded, I aimed toward the
ground & tried to release the safety, but it was jammed. I
then laid the rifle across the seat of a pickup and using
one hand to steady the rifle forced the safety switch
to the fire position. When I did this the gun discharg-
ed. Fortunately no one was injured, except for a large
blood blister on my thumb where I was pressing on
the safety lever, and the only property damage was
a hole through the pickup door.

After the incident, I worked the action several
times and sprayed some lubricant around the bolt
& safety. It now seems to work properly except for
a very stiff trigger.

However I feel something must be asked in the
firing mechanism and I would like your gunsmiths

To Thoroughly check it out.

Untill it is I wouldn't feel safe having a
round in the bush with or with out the
safety on.

Please advise me of your findings.

Respectfully,

John Munday