

RECEIVING AND ESTIMATING REPORT

CUST NO: 019191 C.O.D

COMMENTS

INITIAL CUSTOMER ORDER NO.

DATE RECEIVED 0/30/91 DATE OPENED 11/04/91 DATE CODE EV 10-79 SERIAL NUMBER A6834725 MODEL AND GRADE 700 7MM MAG BDL ORDER R 91-22215

ACCESSORIES SCOPE BASE L/SIGHTS

FROM:

NORTHCRAFTS FIREARMS
STAR ROUTE BOX 70
HOYES RD
FRIENDSVILLE MD 21531
USA

SHIP TO:

NORTHCRAFTS FIREARMS
STAR ROUTE BOX 70
HOYES RD
FRIENDSVILLE MD 21531
USA

COUNT NUMBER ACCOUNT NUMBER N/C WRITE ☐ CLEAN/TEST PROM. DATE ESTIMATED 11-11-91 VIA UPS

PAIR CHARGE TAX INSURANCE UPS PARCEL POST TOTAL

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

Safety malfunctions, causes gun to fire without pulling the trigger.

MAIN FAULT

As received, internal trigger parts are not moving freely - trigger assembly is contaminated with a gummy, sticky residue. Trigger movement is being impeded by above substance in trigger assembly and plates. Trigger pull measured at 6.2 pounds; var. lift is .0095"

REPAIRS

Clear trigger assembly if possible - if not, offer new trigger assembly at normal cost, as a gesture of goodwill

REPAIRMAN DE PROOF CLEAN TEST TARGET PATTERN GALLERY TESTER DATE DATE DATE DATE DATE DATE

OFFICE COPY

RD6925 REV. 7/90

PS04484