

Remington Arms Comp.

Dec. 10, 1991

Attn: Arms Services Div.

14 HOEFER

Ilion, N.Y. 13357

To Whom it may concern:

There Are Two Rifles Enclosed:-

1. 30-06 M-700 BDL AND 2. A

M-600 Mohawk .243 Win. One

needs checked, the other needs repair.

First, the M-700:

This rifle has been in our possession for about 2 years and we have never had any trouble with it. This past hunting season, my wife, (her rifle) on returning to the track, pushed the safety to the off position. The rifle discharged. The safety put a pretty good tear in her thumb. She swears (very safe hunter) that her finger was nowhere near the trigger. We have since heard that some M-700's were recalled for this problem. I tried to duplicate this, but the rifle has worked fine. It needs to be checked by your folks.

(over)

nothing on back

DATE

DATE

RD6925 REV. 1/94

PS04515