


93556

Model: 600



RE00027654

5/18/01

Date Call OK
7/67

I moved the safety to the fire position
& the firing pin released.

Action & trigger assembly
appears that two adj screws have been
re-set. Clean Action &
Replace trigger assembly at NO Charge

Charge 230145