



(518) 587-2783

ED NOONAN

Outdoor Communication

21 Tamarack Trail • Saratoga Springs, NY 12866



www.fishphotos.com
email: enoonan@nycap.rr.com

**Remington Arms
Dennis Sanita
Product Service Department
14 Hoefler Avenue
Ilion, NY 13357**

Dear Dennis,

Per instructions from Tommy Nagle I am enclosing my Model 600, .243 caliber, serial no. 93550 for repair. I recently went on a writing assignment trip to Wyoming to hunt both prairie dogs and Merriam turkeys using the Model 600. Prior to the trip I fired approximately 10 rounds to sight the gun in.

When I uncased the gun in Wyoming for the prairie dog hunt I check the gun before the hunt and found the following problem. After closing the bolt I moved the safety to the firing position and the firing pin released just as if I had pulled the trigger. I reset the bolt several other times and it again happened each time. That evening I tried it again and it worked several times and then the problem started again.





(518) 587-2783

ED NOONAN

Outdoor Communication

21 Tamarack Trail • Saratoga Springs, NY 12866



www.fishphotos.com
email: enoonan@nycap.rr.com

Tom McIntyre of Sports Afield, who witnessed this problem, said he had heard that this model had some safety problems. Hopefully I can get it fixed.

When repaired I will probably take the Model 600 along with the repair slip and trade it in on one of the newer Remingtons.

Thank you

Ed Noonan

