

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00048235 Account # - R-	Description/Serial Number 6281271 Model 700 Center Fire Caliber: 3006 BDL	Date Received - 6/28/2002 Estimate Date - 6/25/2002 Current Date - 7/9/2002
Customer RALPH NUDO 144 WEST 3RD ST NILES. OH 44446 US	Return To RALPH NUDO 144 WEST 3RD ST NILES. OH 44446 US	
Phone (H) (330)-505-0427 Phone (W)	Fax (330)-505-0427 Email POPPA95@AOL.COM	

Reported		Problems	Found
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FO
M238	CLEAN & INSPECT		

Condition		Technician's Comments
ProblemNotes	SHOWS ITS AGE. Action and trigger assembly covered with a heavy sticky substance. Upon receipt the sear/safety cam was seized up. Clean and replace trigger assembly. D.S.	

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
Service Total:		22	


10 LBS 1 OF 1

REXINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

RALPH NUDD
144 WEST 3RD ST
NILES OH 44446




OH 444 0-30



UPS GROUND

TRACKING #: 1Z 114 813 03 1190 6659



BILLING: P/P

INV#: RE00048235

ASC 05.00 J69X/J64X 16.0A 01/2002

PS04601