

RECEIVING AND ESTIMATING REPORT				COMMENTS		STKL ORDER R 91-24830	
INITIAL FPS		CUSTOMER ORDER NO.					
DATE RECEIVED 11/27/91	DATE OPENED 12/03/91	DATE CODE XD 12-83	SERIAL NUMBER B6529376	NEW SERIAL NUMBER	MODEL AND GRADE 700 270 WIN BDL		
ACCESSORIES W/STUDS							
L/REAR SIGHT							
FROM:				SHIP TO:			
OLAVARRI, MARTIN 812 EMERALD BAY RD S LAKE TAHOE USA CA 96150				OLAVARRI, MARTIN 812 EMERALD BAY RD S LAKE TAHOE USA CA 96150			
CUST NO: 053971 C.O.D							
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED
							VIA UPS
GUN CONDITION ☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE						REPAIR CHARGE EXCISE TAX INSURANCE UPS PARCEL POST TOTAL	
CUSTOMER CONCERN CYCLE TRIGGER GROUP BOLT ASSY. BARREL ASSY. REC. ASSY. WOOD METAL AMMO A1 B1 B3 B5 C1 C2 FUNCTION B1 B3 B5 C1 C2 FINISH D1 D2 D3 D4 D5 ACCURACY E1 E2 E3 E4 E5 FIT F1 F2 F3 F4 F5 INSPECT I1 I2 I3 I4 I5							
MAIN FAULT <i>Not able to duplicate above complaints. Trigger and safety assembly operates properly in every respect. Trigger pull measured at 5 1/4 pounds; can lift .510". However, it was noted that trigger assembly and bolt stop were dripping wet with excessive oil. This condition coupled with cold temperatures could conceivably cause internal trigger parts to hang-up.</i>							
PARTS				COMMENTS			
				<i>Offer to clean present trigger assembly or replace trigger assembly at \$100.00 as good-will gesture, if it will better restore confidence in the rifle.</i>			
REPAIRMAN <i>BFL</i>		PROOF		CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER		DATE		DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91

PS04620