

## RECEIVING AND ESTIMATING REPORT

COMMENTS

Product  
SERVICEORDER  
R 95-14617

|                           |                           |           |                           |                   |                                    |
|---------------------------|---------------------------|-----------|---------------------------|-------------------|------------------------------------|
| INITIAL<br>FPS            | CUSTOMER ORDER NO.<br>150 |           |                           |                   |                                    |
| DATE RECEIVED<br>05/11/95 | DATE OPENED<br>05/12/95   | DATE CODE | SERIAL NUMBER<br>A6668099 | NEW SERIAL NUMBER | MODEL AND GRADE<br>700 7MM MAG ADL |
| ACCESSORIES<br>W/STUDS    |                           | L/SIGHTS  |                           |                   |                                    |

DQ 9-78 4TH TIME

FROM:

SHIP TO:

OUTDOORSMAN  
632 BIG HORN AVE  
WORLAND

WY 82401

OUTDOORSMAN  
632 BIG HORN AVE  
WORLAND

WY  
82401

CUST NO:007598 ILIONL

|                                                                                                                                                                                                                                                                 |                    |                                |            |           |                                                                                      |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|--------------------------------|------------|-----------|--------------------------------------------------------------------------------------|
| ACCOUNT NUMBER                                                                                                                                                                                                                                                  | ACCOUNT NUMBER N/C | WRITE <input type="checkbox"/> | PROM. DATE | ESTIMATED | VIA<br>UPS                                                                           |
| GUN CONDITION<br><input type="checkbox"/> NEW<br><input type="checkbox"/> LIGHTLY WORN<br><input checked="" type="checkbox"/> WORN<br><input type="checkbox"/> VERY WORN<br><input type="checkbox"/> UNREPAIRABLE<br><input checked="" type="checkbox"/> MARRED |                    |                                |            |           | REPAIR CHARGE<br>EXCISE<br>TAX<br>INSURANCE<br>UPS<br>PARCEL POST<br>TOTAL <b>35</b> |

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|------------------|------|----------|--------|----------|-----|---------|
| CYCLE            | B1   |          |        |          |     |         |
| TRIGGER GROUP    |      |          |        |          |     |         |
| BOLT ASSY.       | B3   |          |        |          | E2  |         |
| BARREL ASSY.     |      |          |        |          |     |         |
| REC. ASSY.       | B5   |          |        |          | F1  |         |
| WOOD             |      |          |        |          |     |         |
| METAL            |      |          |        |          |     |         |

MAIN FAULT: Mfg. 9/78 firing pin follows down as recd. trig. is not returning. All three adjusting screws have been altered outside of the factory.

|                |                       |          |                                                                                                                                                                             |      |        |         |
|----------------|-----------------------|----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|--------|---------|
| ARTS           | trig. Assy. New Style | COMMENTS | Unable to take trig pull as recd. See engagement is below min factory spec. Connector has been polished outside of factory. Rust on trig pivot hole on housing and trigger. |      |        |         |
| REPAIRMAN      | H.B.                  | PROOF    | CLEAN                                                                                                                                                                       | TEST | TARGET | PATTERN |
| GALLERY TESTER |                       | DATE     | DATE                                                                                                                                                                        | DATE | DATE   | DATE    |

OFFICE COPY

RD6925 REV 1/94

PS04634