

Repair Order Number



Repair Order Number RE00069343	Description/Serial Number E6737131 REPLACEMENT E6739357	Repairman - Robert Frink
Account # - R-	Model 700 Center Fire Caliber: 300 REM	Date Received - 8/29/2003
	ULTRA MAG LAM	Estimate Date -
		Current Date - 9/5/2003
Customer DAVID OSTLIE 1954 PATRICK PLACE CORCORAN, MN 55340 US		Return To DAVID OSTLIE 1954 PATRICK PLACE CORCORAN, MN 55340 US
Phone (H)	Fax	
Phone (W)	Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FOR
M992	FIRE WHEN TURNING OFF SAFETY	M139	RIFLING ROUGH / MISCUT / DAMAG
M993	REPLACE BARREL WITH 29 OR 30"		

		Repair			
Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F109821	700 UM BBL ASSB 300 REM UM - POL 26"	1	1	0	Y
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		2	2	0	
Service					
4000119	GR-TEST	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000117	GR-PROOF	1	1	0	Y
Service Total:		2	2	0	

ProblemNotes All 3 trigger adjustment screws re-set. Replace trigger assembly complete and check rough bore.
NOTE - 26" bbl only type available.

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date