

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Service

ORDER
R 94-25615

INITIAL CUSTOMER ORDER NO

JJM

DATE RECEIVED

09/06/94

DATE OPENED

09/07/94

DATE CODE

WX 8-73

SERIAL NUMBER

6661073

NEW SERIAL NUMBER

MODEL AND GRADE

700 270

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

OWENS, HERMAN, JR
306 BROOKWOOD DR
DUNCANVILLE

TX 75116

SHIP TO:

OWENS, HERMAN, JR
306 BROOKWOOD DR
DUNCANVILLETX
75116

CUST NO: 103001 C.D.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

9/12/94 UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE 20.00

EXCISE

TAX

INSURANCE

UPS 8.00

PARCEL POST

TOTAL 28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.				D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Left mfg 1923, upon receipt, we could not duplicate the customer's concern. Examination revealed that the trigger adjustment and stop were loose. The action and trigger assembly are covered with a greasy, sticky substance. The bolt stop action is noisy. Trigger - 5 lbs. 500 ft/lbs - .001

PARTS

COMMENTS

#26345 1/5, no bolt lock. Replace the trigger trigger assembly and clean the action at 1/2 normal replacement cost, as a gesture of good will go ahead.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD0828 REV 1/94

PS04659