

✓

March 22, 1994

Remington Arms Company, Inc.
Arms Service Division
Ilion, New York 13357


Ref: Remington Model 700, 30-06, Ser. C6825303

On March 9, 1994 I purchased a Remington 700 from The Sports Authority, in Glen Burnie, Maryland. When I got the weapon home I broke it down in order to clean it. In the process I removed the bolt. After cleaning the weapon, I began to re-assemble it. I replaced the bolt and as I locked it down, the weapon discharged. I don't know if I had done anything to the safety assembly. At the time it discharged I wasn't too concerned, thinking this was normal when replacing the bolt into the gun.

As you know this past Sunday 60 Minutes did a segment about the accidental discharge of the model 700. Now I am concerned. Although I have since tried to repeat the discharge, it has not happened again. However I can never feel comfortable about the possibility of an accidental discharge while the weapon is loaded.

I like the rifle very much and only purchased it because it was the one I always wanted. I am now concerned that the weapon is not safe. Please advise what adjustment and/or correction can be made that would prevent any future accidental discharge.

Sincerely



Daniel R. Olds
3024 Marlin Dr.
Riva, Md 21140

(410) UNLISTED