

Serial Number: **E63371** 102

Model: 700



RE00025967

FROM: **OSHMAN'S** STORE NO. 1451
SUPERSPORTS USA
 ADDRESS 166 Gateway
 CITY Beverly STATE TX ZIP 77701

TO: Remington Arms

ADDRESS 14 HOFELER
 CITY ILION STATE NY ZIP 13357

RETURN TO VENDOR

VENDOR: Refer to this Number in any correspondence.

DEBIT MEMO NO. H 32826

KEY REC NO 618405

RETURN AUTHORIZATION NO NONE

SHIP DATE 3/27/01

CARRIER UPS

BILL OF LADING NO 03/0038248

NO. OF PIECES 1 WEIGHT 10

☒ PREPAID ☐ COLLECT AMOUNT \$

PREPARED BY

PACKED AND CHECKED BY

VENDOR NO.

☒ CHECK ONE
☐ ISSUE CREDIT MEMO FOR YOUR RECORDS. WE ARE CHARGING YOUR ACCOUNT FOR THE FOLLOWING REASON (SEE COMMENTS BELOW):

ATTN VENDOR: DO NOT RETURN MDSE SENT FOR CREDIT

NEW MERCHANDISE, DEFECTIVE

USED MERCHANDISE, DEFECTIVE

___ DUPLICATE SHIPMENT

 OVER SHIPMENT

____ DID NOT ORDER MERCHANDISE

___ PO. CANCELLED

___ PURCHASE ORDER AGREEMENT NOT MET

X REPAIR/REPLACE FOR THE FOLLOWING REASON.

☒ PLEASE REPAIR OR REPLACE, NO CHARGE

— MERCHANDISE FOR REPAIR, STILL UNDER WARRANTY

☐ OTHER (PER VENDOR INSTRUCTIONS)[illegible]

ALL SHIPMENTS ARE
F.O.B. ORIGIN

Total Merchandise Cost	44,723
------------------------	--------

Inbound Shipping Costs

Return Shipping Costs

Handling Charge

DOCUMENT TOTAL

COMMENTS

Fires when taken off safety - w/c

Action slightly dirty, rust found on trigger hole - replace
Trigger Assm & clean action 1/2 M5P