

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00046032	Description/Serial Number 6466969	Date Received - 5/7/2002
Account # - R-	Model 700 Center Fire Caliber: 30 06 BDL	Estimate Date -
		Current Date - 5/10/2002
Customer JOHN PETERSON 428 HILLSIDE RD KING OF PRUSSIA, PA 19406 US		Return To JOHN PETERSON 428 HILLSIDE RD KING OF PRUSSIA, PA 19406 US
Phone (H) (610)-285-5926		Fax
Phone (W)		Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M238	CLEAN & INSPECT
M238	CLEAN & INSPECT	M239	REPLACE TRIGGER ASSEMBLY
M992	UNINTENTIONAL FIRING		

Technician's Comments	
Problem/Notes	Trigger assy. and action are dirty and rusty (poor care). Replacing trigger assy. and cleaning action per safety modification program.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		23	


10 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

JOHN PETERSON
428 HILLSIDE RD
KING OF PRUSSIA PA 19406




PA 193 9-02



UPS GROUND

TRACKING #: 1Z 114 813 03 1188 1604



BILLING: PREPAID

INV#: RE00046032

ASC 3.70 J69X/J64X 14.0 01/200