


Serial Number: 333756

Model: 700



RE00052535

9/23/02

Date Code

ULR

2/68

Ref. fired when disengaging the safety

The action, mag. spring & trigger assembly covered
with a heavy brown sticky substance.

Poor maintenance.

Clean action & replace trigger assembly \$20.00
Quote