

Serial
Number:

T6242160

Model: 700



RE00048105

6/21/02

When I use the belt the trigger goes off.

Date Call
LS 2/8

Reamer & trigger assembly components rusty - replace
poorly maintained.

Clean action & replace complete trigger assembly at
Spec. Price 1/2 MSP JP [Signature]