

Repair Order Number



Repair Order Number RE00052766	Description/Serial Number E6657290	Repairman - Robert Frink
Account # - R-	Model 700 Center Fire Caliber: 243 ADL	Date Received - 9/30/2002
	SYN YOUTH	Estimate Date -
		Current Date - 10/8/2002
Customer PAMELA PHILLIPS 30 BROOKMEADOW WIMBERLEY, TX 78676 US		Return To PAMELA PHILLIPS 30 BROOKMEADOW WIMBERLEY, TX 78676 US
Phone (H) (512)-847-5729 X602		
Phone (W) (512)-847-9642 XW	Fax	
	Email	

Reported		Problems	Found
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE
M992	FIRED WHEN TAKEN OFF SAFE		

Material #		MaterialDesc	Repair	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part							
F26345		700 TRIG ASSB RH		1	1	0	Y
Part Total:				1	1	0	
Service							
4000119		GR-TEST		1	1	0	Y
4000104		ARMS SERV SHIPPING & HANDLING		0	0	0	Y
4000118		GR-CLEAN		1	1	0	Y
Service Total:				2	2	0	

ProblemNotes	Could not duplicate. Trigger assembly has sticky residue. Install a new trigger assembly and clean action at n/c. FLS 10/1/02.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date


9 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFER AVE
ILION NY 13357

SHIP

TO:

PAMELA PHILLIPS
30 BROOKMEADOW
WIMBERLEY TX 78676




TX 786 0-02



UPS GROUND

TRACKING #: 1Z 114 813 03 1195 9012



BILLING: P/P

INV#: RE00052766

ASC 05.00 J69K/J64X 16.0A 01/2002