

Serial
Number:

6449938

Model: 700



RE00051602

9/4/02

Date Chk
PO
6/77

Auton & tug arm covered
with dirt, rust & sticky substance.
Pin needle found inside auton. Left
poorly maintained.

Replace tug arm & auton \$20.00

Quote