

To Whom it May Concern,

this is my Remington Model 700 (S/N 6449938)

that I'm sending in for the safety recall.

The gun has fired prematurely twice. *Butt Cook*

Both times while unloading. Once *PD*

before the installation of the floor plate, *6/11*

Once afterward. Both times while

working the bolt. The scope mounts

must be glued in and I can't remove them.

Our hunting season starts now so if the

gun will not be ready or other problems

arise please notify me ASAP. *PTAK*

*Mike PTA*

Work (734) 324-5059 3865 18th

Home (734) 283-2554 Wyandotte, MI 48192