

Number

A0851654

Model: 700



RE00043733

3.18-02

REMINGTON ARMS CO.

SIR

ENCLOSED IS MY
REMINGTON MODEL 700 BOLT
- 243 CAL. SER. NO. A 6851654
WITH BOLT NO. 1654

THIS GUN WAS PURCHASED
NEW. THIS GUN HAS BEEN
HUNTED TWICE AND ON BOTH
OCCASIONS IT HAS FIRED
INADVERTLY WHEN THE BOLT
WAS RAISED TO REMOVE THE
LAST ROUND FROM THE
CHAMBER

THIS ACTION CAN BE
REPEATED ABOUT ONE (1) OUT
OF FOUR (4) TIMES BY
RAISING THE COCKED BOLT
ON AN EMPTY CHAMBER

9/23/02

Upon receipt we could not duplicate the
reported concern. Upon noted that & great
on the action & trigger housing assembly. Per Call
Replace trigger assembly & clean \$20.00 per safety mod. 100.

I RECENTLY BECAME
AWARE, WHILE LISTENING TO
A RADIO TALK SHOW, THAT THIS
PROBLEM IS COMMON TO THE
MODEL REMINGTON AND IS THE
THE RESULT OF BEING
MISHANDLED.

PLEASE ADVISE WHAT
ACTION YOU CAN TAKE TO
MAKE THIS A SAFE FIREARM

THANKS

JOHN L PULLMAN
3026 PRESCOTT ST
HOUSTON, TEXAS
77025