

EIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R92-27422

CUSTOMER ORDER NO

CEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
3/92	2/14/92	RY 11-74	6800645		700 30-06 BDL
ORIES	W7STUDS				

SHIP TO:

PITTS/WILLIAM L
8789 LEE RD
LITHIA SPRINGS

GA 30057

PITTS/WILLIAM L
8789 LEE RD
LITHIA SPRINGS

GA
30057

CUST NO: 071847 C.O.D

NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM DATE	ESTIMATED	VIA UPS
DITION	UPS C.O.D.				REPAIR CHARGE
ELY WORN					EXCISE
IN					TAX
Y WORN					INSURANCE
EPAIRABLE					UPS
RED					PARCEL POST
					TOTAL 25.00

MER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
R GROUP						
SSY						
ASSY.						
SY						

"Gun fired on its own"
purchased rifle used per phone 1/5/93

Unable to duplicate Customer's Complaint. However, upon
disassembly, gummy brown substance found on bolt stop
and on trigger assembly. Gun is not responsive. Per phone, cleaning
rod and trigger assembly replaced.

COMMENTS

Based on condition, offer to
replace trigger assembly at 1/2 normal
cost, as feature of good will.
Mr. Pitts approved per phone 1/5/93

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS04846