

RECEIVING AND ESTIMATING REPORT

INITIALS	CUSTOMER ORDER NO.	ATTN: DENNIS SANITA			
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/16/93	11/19/93	LX 2-73	6621627		700 243 WIN ADL
ACCESSORIES		W/STUDS HARD CASE SCOPE BASE			

FROM:	SHIP TO:
PALMOUR, HAROLD M. 4565 FM 3126 LIVINGSTON TX 77351	PALMOUR, HAROLD M. 4565 FM 3126 LIVINGSTON TX 77351

CUST NO: 087630 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM DATE	ESTIMATED	VIA
					UPS
GUN CONDITION					REPAIR CHARGE
☐ NEW ☐ LIGHTLY WORN ☒ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED					2
					EXCISE
					TAX
					INSURANCE
					UPS
					PARCEL POST
					TOTAL 3

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5			E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			
MAIN FAULT: Rifle mfg. 1973. Upon receipt rifle inoperative. Trigger would not move or retract, bolt stop also would not move upward when depressed. Examination revealed action and trigger assembly covered with a heavy greasy, and sticky substance. Structural parts also jammed up. Subst. has been removed from the trigger adjustment & stop screws indicating they have been tampered with outside the factory. Poor maintenance. Replaced trigger screws. Clean action at 1/2 normal rpm. Cost, as quoted by good work.						
PARTS		COMMENTS				
5398 8000 0770 4374		REPAIRMAN				
App Jan 95		MOOF				
Phone 409-566-4033		CLEAN				
		TEST				
		TARGET				
		GALLERY TESTER				
		DATE				
		DATE				
		DATE				

OFFICE COPY

RD6925