## THE PALMOUR GROUP


November 10, 1993

AH AICE AICE

HAROLD H. PALMOUR DORTHA M. PALMOUR

Remington Arms Company, Inc.

Product Service 14 Hoefler Avenue Llion N. Y. 13357



Attention Mr. Sonita

Dear Mr. Sonita,

Re my telephone conversation of November 9, 1993, concerning my Model 700 rifle.

The problem is it will fire when chambering a round or when a safety is pushed forward.


I shipped it to your attention by U. P. S. today and you should receive it Friday, November 12, 1993, or Monday, November 15.

Please advise what caused the problem and what you can do to fix it. We are very fortunate no one was injured because of this malfunction.

Sincerely,


Harold Palmour

Copy - File



**ROUTE/8/BOX/428**, LIVINGSTON, TX 77351-9104

4565 FM 3126



Remington Arms Company, Inc. Product Service 14 Hoefler Avenue

Ilion, N. Y. 13357

Attention: Mr. Sonita

am ladadadadahaladil