

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL CUSTOMER ORDER NO

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

MODEL AND GRADE

ORDER

11/29/90

12/04/90

A6775475

700 7MMNAG

BDL/LH

R 90-31383

ACCESSORIES

W/STUDS

PV 6-79 2ND TIME IN

FROM:

SHIP TO:

PIDGION ROAD SHOOTING RANGE
ROUTE 4 BOX 257
STEPHENVILLE TX 76401

PIDGION ROAD SHOOTING RANGE
ROUTE 4 BOX 257
STEPHENVILLE TX
76401

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"... The gun discharges when safety is moved from safe to fire."

MAIN FAULT

Cannot duplicate complaint. However, firing pin will sometimes follow down when bolt is closed properly. Trigger assembly has been completely mis-adjusted & faulty, as evidenced by foreign sealant. Trigger pull below min. spec (22"), rear engagement inadequate, overall inadequate.

PARTS

Send quotation for replacement trigger assembly.

Customer should be told not to attempt adjustments to trigger assembly!!!

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE