

RECEIVING AND ESTIMATING REPORT

INITIAL FJB		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 10/09/90	DATE OPENED 10/16/90	DATE CODE	SERIAL NUMBER A6428840	MODEL AND GRADE 700 30-06		BDL/LH	ORDER R 90-2685

ACCESSORIES

L/ STUDS

FROM:

PORTER, KENNETH
A.O. PORTER CO
SCULPS HILL RD
AUBURN PA 17922

SHIP TO:

PORTER, KENNETH
A.O. PORTER CO
SCULPS HILL RD
AUBURN

PA
17922

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☒ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"000 gem fired twice when I pushed the safety off."

MAIN FAULT

Trigger assembly is rusted - exterior & interior - with hammer
rust at sometime and was not properly maintained - bottom of frame
also has rust.

PARTS

Send repair quotation to replace
trigger assembly at 1/2 replacement
as gesture of good-will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 6

PS04888