

Date: 3/4/05

By: Bruce Travis Sr.

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Palm Bch. Shen. Office

R.E. Number: 93948

Reason for inspection: Fir pin Ralls when engaging safe or touching bolt head.

FIREARM

Manufacturer: Rem. Model: 700

Serial Number: C6227197 Date of Manufacture: 4/88

Overall external condition: Painted w/damo

Barrel condition: After mkt.

Receiver condition: OKAY

Stock condition: After mkt.

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: —

Adjustments/alterations: —

Other: After mkt.

Headspace: —

Function evaluation:

Feeding: _____

Extraction/ejection: _____

Trigger pull: _____

Manual safety: _____

Test firing results (if applicable): _____

DISPOSITION

Trig. plate assm. + bbl. are not of Rem. mfg. Fin.
pin falls as bolt is lifted. Replace TPA at 22% less
normal charge. check over safe operation & return.
ADDITIONAL COMMENTS Quote