

**Remington Arms Company,
Inc.**

970 Remington Dr. P.O. Box 700

Parts/Repairs 800-243-9700
Fax 336-548-7801

www.remington.com info@remington.com

**REPAIR
DOCUMENT**

**REPAIR
DOCUMENT**

Repair Order Number RE00101065 Account # - R-	Description/Serial Number 7634440 Model 7 Center Fire Caliber: 308 WIN	Date Received - 10/12/2005 Estimate Date - 9/21/2005 Current Date - 10/31/2005
Customer GREG PURYEAR 111 NORTH NOBLE P.O. BOX 622 WHITEHALL, MT 59759 US		Return To GREG PURYEAR 111 NORTH NOBLE P.O. BOX 622 WHITEHALL, MT 59759 US
Phone (H) Phone (W)	Fax Email	

Reported		Problems	Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FO	
M992	FIRES UPON RELEASE OF SAFETY			

Technician's Comments	
Condition	SCRATCHES THROUGHOUT
Problem/Notes	Trigger assembly very dirty / sticky causing sear cam to stick to sideplates. Replace trigger assembly and clean action for 1/2 MSP.
<i>Yellow Copy</i>	

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F92458	7 TRIGGER ASSB	1	N
	Part Total:	1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	N
4000118	GR-CLEAN	1	N
4000119	GR-TEST	1	N
	Service Total:	2	
<i>Not shipped</i>			